5. RECOMMENDED ACTION

5.1 Site CPP-61

It is recommended that Site CPP-61 be a "No Further Action" site. The analytical data show that the average residual PCB contamination at CPP-61 is ≤ 10 ppm. The contaminated area was excavated to 78 in. below ground surface (bgs) and backfilled with excavated soil containing no more than 10 ppm PCB contamination. Based on the data in Table 2-2, much of the soil contained <0.5 ppm PCB, making the average backfill soil much less than 10 ppm.

The residual PCB contamination at CPP-61 is below the 10 ppm agreed to in 1987 with the EPA Region X Office in Seattle for the cleanup. In addition, the residual PCB contamination is below the current spill TSCA cleanup criteria for a low-concentration PCB spill for outdoor electrical substations (\leq 25 ppm) and restricted access boundary locations (such as INTEC) (\leq 25 ppm); and the soil greater than 10 ppm was removed to 78 in. bgs, which is more than the depth of 10 in. required for a residential area.

5.2 Site CPP-81

It is recommended that Site CPP-81 be a "No Further Action" site. All evidence indicates that no release has occurred at this site and that the potential threat of contamination in the pipe has been removed. The analytical data indicate that the residual levels of cadmium (0.17 mg/kg) and total chromium (0.112 mg/kg) in the pipe are below regulatory concerns (Cd 1.0 mg/L and Cr 5.0 mg/L). The residual level of mercury in the pipe was calculated to be 0.0004 mg/L (see Section 3.5.1 for decontamination calculation) and is below the regulatory concern for mercury of 0.2 mg/L. These residual concentrations are below the 1E-06 and HQ = 1 risk-based concentrations for industrial and residential areas (see Tables 3-4 and 3-5).

5.3 Site CPP-82

It is recommended that no further actions be taken at the locations associated with Site CPP-82.Location A, B-1, B-2, B-3, and C are recommended as "No Further Action" sites.

Location A

All contaminated soil above background (300 cpm, the typical cold area at INTEC in 1987) was identified, collected, and disposed at RWMC. Health physics personnel confirmed that the spill was small and localized; the contamination was easily identified; and all soil showing activity levels above background was removed. Any residual TCE, cadmium, or mercury would be below RCRA hazardous levels, as these are below RCRA hazardous levels in Tank SFE-126 sludge, which collected the wastewater.

Location B

There are no residuals at Locations B-1 and B-3, as the lines at these locations were not ruptured. At Location B-2 about 25 gal of liquid was released from line XW-NL-129167. This line did not contain hazardous or radioactive contaminants and the liquid was maintained at about pH = 7. The levels of any chemicals in the water were below the RCRA hazardous levels. Line CT-NC-125271 contained steam condensate that did not contact any process fluids and remained as treated water; thus, liquid from this line was nonhazardous and nonradioactive.

Location C

Any residual contaminants at Location C from the rupture in line SW-NH-110717 are below the toxicity values for RCRA hazardous metals (all <0.5% of their respective toxicity levels) and below the 1E-06 and HQ = 1 risk-based concentrations for industrial and residential areas (see Tables 4-2 and 4-3). Line SW-NH-110718 contained no hazardous or radioactive contaminants, only minerals already present in the groundwater.

6. REFERENCES

- 15 USC 2601 et seq., 1976, "Toxic Substances Control Act," United States Code.
- 40 CFR 261.24, 2001, "Toxicity characteristics," *Code of Federal Regulations*, Office of Federal Register, January 1, 2001.
- 40 CFR 761.125, 2000, "Requirements for PCB spill cleanup," Code of Federal Regulations, Office of Federal Register, July 1, 2000.
- DOE-ID, 1992, Track 1 Sites: Guidance for Assessing Low Probability Hazard Sites at the INEL, DOE/ID-10340(92), Rev. 1, July 1992.
- DOE-ID, 1997a, Comprehensive RI/FS for the Idaho Chemical Processing Plant OU 3-13 at the INEEL—Part B, FS Report (Final), DOE/ID-10572, November 1997.
- DOE-ID, 1997b, Comprehensive RI/FS for the Idaho Chemical Processing Plant OU 3-13 at the INEEL—Part A, RI/BRA Report (Final), DOE-ID-10534, Rev. 0, November 1997.
- DOE-ID, 1999, Final Record of Decision, Idaho Nuclear Technology and Engineering Center, Operable Unit 3-13, Idaho National Engineering and Environmental Laboratory, Idaho Falls, Idaho, DOE/ID-10660, Rev. 0, October 1999.
- DOE-ID, 2000, Operable Unit 3-14 Tank Farm Soil and Groundwater Phase I Remedial Investigation/Feasibility Study Work Plan, DOE/ID-10676, Rev. 0, December 2000.
- EMI, 1997, Hazardous Waste Determination, Waste Area Group (WAG) 3 RI/FS Operable Unit (OU) 3-01 (CPP-61), CPP-61 Soils Samples OU 3-01, Lot No. 3-37b, Environmental Management, Inc., April 3, 1997.
- EPA, 1990, Guidance on Remedial Action for Superfund Sites with PCB Contamination, OSWER Directive 9355.4-01, EPA/540/G-90/007, Environmental Protection Agency, August 1990.
- EPA, 2000, Preliminary Remediation Goals, http://www.epa.gov/region09/waste/sfund/prg/index.html, web page updated November 2000, web page visited August 28, 2001.
- Newby, B. J., 1979, Calcining Sodium-Bearing Waste by Blending with Zirconium Fluoride Waste, ENICO-1006, Exxon Nuclear Idaho Company, Inc., November, 1979.
- Newby, B. J., 1980, *Calcination of Dilute Zirconium Waste*, ENICO-1042, Exxon Nuclear Idaho Company, Inc., November 1980.
- Raunig, Dennis E., LMITCO, to Roger K. Jones, LMITCO, February 17, 1998, "Disposition of an Investigative Derived Waste (IDW) DER-001-98," File Code 6105.
- SAIC, 2000a, "Idaho Nuclear Technology and Engineering Center, WAG 3 OU 3-14 White Paper Evaluation CPP-61 PCB Spill in the CPP-718 Transformer Yard," Science Applications International Corporation, October 2000.

- SAIC, 2000b, "Idaho Nuclear Technology and Engineering Center, WAG 3 OU 3-14 White Paper Evaluation CPP-81 Abandoned CPP-637/CPP-620 VOG Line," Science Applications International Corporation, October 2000.
- SAIC, 2000c, "Idaho Nuclear Technology and Engineering Center, WAG 3 OU 3-14 White Paper Evaluation CPP-82 Underground Pipe Incidents," Science Applications International Corporation, October 2000.
- WINCO, 1992a, Track 1 Documentation Decision Packages for WAG 3 OU 3-01 Sites CPP-49, CPP-50, CPP-51, and CPP-61, Document 5201, Rev. 0, Westinghouse Idaho Nuclear Company, Inc., 1992.
- WINCO, 1992b, Track 1 Documentation Decision Packages for WAG 3 OU 3-12 Site CPP-82, Document 5292, Rev. 1, Westinghouse Idaho Nuclear Company, Inc., December 1992.
- WINCO, 1994, Track 1 Documentation Decision Packages for WAG 3 OU 3-12 Site CPP-81, Document 5735, Rev. 2, Westinghouse Idaho Nuclear Company, Inc., April 1994.